



**TINKER & RASOR**

POWER



0.5 A

1.0 A

Power Supply: 1.5V  
9V (9V battery)

### MODEL A AMP CLAMP TESTER

DC Current Source  
Verify the Accuracy of  
Amp Clamps and Current Meters



www.tinker-rasor.com

CALIBRATION  
ILLUMINATION

Use Supplied  
Charge Only  
CHARGING JAR

Made in USA

**OPERATION PRECAUTIONS**

1. This device is designed to be used as a DC current source for calibrating amp clamps and current meters. It is not to be used as a power source for other devices.

2. The device is powered by a 9V battery. The battery should be replaced when the device is not in use for an extended period of time.

3. The device should be stored in a dry, cool place. It should not be exposed to moisture or extreme temperatures.

4. The device should be handled with care. It should not be dropped or subjected to physical shock.

5. The device should be used in accordance with the instructions provided in this manual.

**TINKER & RASOR**